


conduit fitting now
located at base,
(was forward, in
middle of spring)

insulator and PMT
centering sleeve

will Cu be OK with
a helicoflex
gasket?

careful design
required here, to
avoid interference
with optical gel or
can (



flat blind threaded holes needed

maybe mount capacitor to underside of base?

